資 料

新しい照度基準に関するブラックウェル氏の研究[†]

正会員 野 崎 道 雄*

1. は し が き

Richard Blackwell は心理学者でミシガン大学の視覚研究所長である。彼は 1950 年から IERI (Illuminating Engineering Research Institute) の援助を受け新しい照明基準をえるための基礎的研究を行っていた。一方 ES が推奨照度 (recommended lighting levels) の新しい値をえて Handbook を発刊せんとしてブラックウェル等の協力を求めたのである。

ここで筆者は 1958 年 3 月 IERI の Research Symposium の席上ブラックウェルが、それまでの研究について口述した記録を基にして、彼の研究の概略につき解説したいと思う。

2. 視覚の容量の概念 (Visual Capacity Concept)

彼のいう視覚の容量の概念とは静止の状態にある眼 (static eye) に information が入ってくると受動的にこれを同化するのであるが、毎秒幾つの information を同化するかということであり、APS (Assimilation per seconds) でそれを表わしている。すなわち 1 APS とは 1 視作業に 1 秒の時間を要するのである。

これについてまず彼の行った実験は調節以外には目の働きもしないような特殊の場合の眼についてのできるだけ簡略化した実験であって、二つの supra-threshold の刺激光をある間隔を置いて続けて送り、その間隔をどれだけにしたなら二つの光として見えるかというのである。これによると 1/1000 秒の持続時間の刺激光を続けて送ると、約 1/10 秒すなわち約 100 msec の間隔があれば二つの光として見えるのがわかったと述べている。したがってこの実験で maximum visual capacity として 10 APS が提唱されるわけである。

さらにもう一つの少し複雑な実験として彼が示しているのは同じく二つの刺激光を提示するのであるが、今度は二つの光の存在を見出すことを要求するものであってここに Contrast の問題が入ってきている。

第 1 図において、ある puls の光が提示されたとすると、その single puls を見るのにあるコントラストが必要と

なる。それが B で示される。二つの puls が提示されると、どんな場合でもそれらは助け合

って一つだけの場合 B よりコントラストは少なくともすむわけであり、二つの puls の間隔を接近させると A で示すように、あ

たかも一つの puls が 2 倍の持続時間になったかのように見える。このグラフについて見るに二つの puls の間隔が長くなると、それを見るのによりコントラストを必要とするのでカーブは上昇し B と同じになり、さらに間隔を長くすると、コントラストは再び低下する。ここで $-1.3 \log \text{ seconds}$ のあたり約 50 msec 附近は visual system にとっては independent aspect であって二つの刺激光は全く助け合わない。この点を時相の交軌点 (temporal node) と呼んでいる。また $-1.7 \log \text{ seconds}$ 約 20 msec 以下の間隔では visual system は一つの光から二つを見分けることが出来ない。すなわち二つの要素の間が離れると visual mechanism の cycle は新しくなっていく。

結局、visual System が静的に働き、実験者により Control された simple な二つの information が送られると、この information の二つの要素が 1/10 秒で分けられて visual System は循環するとしている。

そしてここで information を同化して maximum capacity に近付けるためには、適当なる lighting condition が必要になるというわけである。

なお visual system が毎秒 10 回の周期をもつという点に関しカリフォルニア大学の Donald Lindsley 教授の電気生理学的実験例を挙げている。それは猿を用いた electrical response であって、これを見ると明らかに visual system がよい cycling system であって毎秒 10 回循環し、最も感受性の高い peak をそこに持っているのがわかるそうである。

以上は静止状態の眼 (static eye) について見たのであるが、次に動的な眼 (moving eye) についての実験から次のように述べている。moving eye については以

第 1 図 視標の対比と 2 刺激光の間隔時間との関係

[†] M. Nozaki : Mr. Blackwell's Research concerning the New Standard for Illumination Level

* 慶応義塾大学医学部

前より読書の際の ophthalmographic technique が用いられているが、これでえた固視休止 (fixational pause) の平均値は240~225msec 約 1/4 秒であり、眼は全体の時間の約 10% を ocular movement に、約 90% を fixational pause に用いているのがわかる。

さてここで visual System が視野内で neural scanning を有していると考える。すると被検者が真直ぐ前を見ていて視野内のかけ離れた部位に information を置くとすると、同時に二つの相を見て、二つの中の一つを期待すると発見の確率は減ずるのであって空間の wrong part に又、sensitivity cycle の wrong part に information を送ると実際に同化する capacity の25%までも視作業の能率は減じて悪くなるのである。

3. 標準視作業に対する基礎研究

1950年彼は初期の研究で基本的な最も簡単な実験として information が2元であるもの、すなわち light flash を用いてその存在の有無を返答させることをした。

実験装置の外観は第2図に見るごとくで被検者は椅子に腰掛けており、この室は均一にも不均一にも照明しえて、約1000 foot lambert

第2図 静的な眼による実験

るようになっている。被検者の前にあるのが transilluminated screen で、この後に target (視標) を置き、後から光を照らすのである。その光の intensity, size, exposure duration が調整可能になっている。実験は静止状態にある眼を用いて固視点を見させて置き target を提示し、被検者は釦を押すだけでその response は電子計算機付属の自動装置で整理記録される。ここで視標のコントラストと正答率の関係を示す曲線はS字状の視覚の頻度曲

第3図 視標のコントラストと背景輝度との関係(5APSの場合)

線に一致したものとなる。彼は accuracy level として50%をとるのが誤差が少なくて良いとしている。そして露出時間 1, 1/3, 1/5, 1/7, 1/10秒、視標の直径、視角1, 2, 4, 10分につい

第4図 視標のコントラストと背景輝度との関係(10APSの場合)

下げていった点であり、このグラフにより既知の reflection factor から illumination value を計算しえて、またある APS の仕事にはどれだけの明るさを必要とするかがわかるわけである。

これまでは均等な背景についてであるが、次に不均等な背景についての効果として glare のある場合の実験と視野の下半、上半を明るく又は暗くした実験を行っている。それによるといずれもコントラストを上げねばなら

第5図 光幕の輝き (veiling brightness) のコントラストに対する効果

第6図 視野の上下半を明暗にしその境界線から視標の離れ(視角)のコントラストに対する効果

いのは当然であるが、第5図は種々な比率の veiling brightness について、そのコントラスト上昇の具合を示した。また第6図は視野の下半を暗く、上半を明るくして暗い方に視標を置き、その境界の水平線からの距離を視角で表わして5, 10分および丁度境界線上について見ている。

4. 域値に乗ずる可視度係数

(Supra-threshold Visibility Factors)

第3図、第4図にその一部を示したが種々の APS の視作業について、彼がえたグラフは50%正答率の域値を表わしたものである。推奨照度を定めるに当り、この threshold seeing よりも明るく照明せねばならぬのは当然である。しからばどの程度にその水準を引き上げたら良いかということになってくる。

さてここで問題になるのは実験室で実験する場合と、

実地に眼を用いる場合とでは、明らかに差異があることである。実験室では休息もし安楽な状態であり時間も限られ疲労は少い。しかも被検者は規対象物たる information の現れる時と内容と場所を予め知っている、ところが実地にはその中のあるものが欠如している、information のすべてまたはその一部が欠如した場合にコントラストは2倍にせねばならぬのを彼は以前に見出している。したがって実地条件下では先づ実験室でえた成績の2倍のコントラストが必要であるといっている。次に実地作業では information の現れる位置を両眼同じ状態で正しく見て

第7図 Field Task Simulator 実地視作業に模した実験装置

はいない。すなわち通常対象物より少し離れた所を見ている。そこで注視すべき対象物から眼が離れた場合

に、それを補うためにコントラストをどれだけ上げなければならないかという問題が生じるのであるが、実験的に次の結果をえている。それは 1° —1.6倍、 $1\frac{1}{2}^\circ$ —2.5倍、 2° —4倍である。 2° という読書距離 14 inch の場合に約 $\frac{1}{2}$ inch がそれに当るわけである。

次に彼が紹介しているのが実地視作業に近い実験装置とその結果で第7図がその外観である。これを Field Task Simulator と称し直径 8 feet の輪に50箇の 4 inch

第8図 基礎実験データと Field Task Simulator によるデータの比較

置いて、異った輝度のものを中から見つけ出し、被検者は鈕を押してそれを示すのである。これにより実地に行なわれる視作業と似ていると考えるわけである。まず 1 APS の視作業として輪の 1 回転を 50 秒とした。その結果を基礎実験の 1 秒に 1 つの single pulse の刺激光を見せたものと比較すると第8図のようになる。この図で実線が基礎実験のデータで白丸で示したのが Simulator でえたデータである。一番上の点線は basic curve を

logarithm の 6.0 に等しい距離だけ単に引き上げたものである。

さて基礎実験と J の Simulator による方法との明らかな差異はというと、後者では輪が廻転してきた時に黄斑部の中心窩で light spot を見てはいないことである。

第9図 Eccentricity の視標コントラストに対する効果

第9図は三つの背景輝度について視標が視軸から離れている場合にさらに追加すべきコントラストを示した。これで見ると off-axis seeing には可成りのコントラストを余分に必要とし、それは背景輝度の高い方が大である。つまり実地視作業で dynamic に眼を用いた場合には eccentricity factor が入って来て背景輝度の高い程不利になってきている。

基礎実験でえたデータを実地視作業に応用するに当たって、どれだけの係数を乗せねばならぬかということ、まず第8図でわかるように Simulator で pre-information のない場合には約 2 倍のコントラストがさらに必要となっている。また、実験室における実験と実地視作業とで異なる点は、実験室では light spot が存在するか否かということだけであるが、実地にはさらに一段と進んだ認識過程を必要とするということである。被検者が実験によく慣れた人間であるかどうかということも影響がある。それについては彼は以前に未経験者 77 人を集めて実験の練習をして、その前後の成績を比較しコントラストについては 2.4 倍になるのを見ている。

したがってここで eccentricity factor が 2.5, information の欠如が 2.0~2.5 でその両者を field factor とし

第10図 視作業定量機 Visual Task Eysenator

て 6.0, それに練習効果を 2, 4 として、これらの総合の約 15 という値が域値に乗ずる可視度係数として提唱するのである。

5. 視作業定量機 (Visual Task Evaluator)

これは今までに得られた資料を実際に応用する為に作

った機械で第10図がその外観である。この機械の idea は決して新しいものでなく Luckisch and Moss の時代の Visibility Meter にさかのぼる。つまりある未知の実地視作業のコントラストを域値まで下げて、同じ条件の標準の視標に等価させるのであり、ある視作業についてその上を一樣な明るさで覆い明るさを段々上げていってその視作業の図形がやっと見える所までコントラストを下げる。それから別の光学系がセットされて標準の視標、ここでは視角4分の円形の視標が用いられているが、これを実地視作業と同じ条件で同様に域値までコントラストを下げる。これで両者が見え方の点で等しくなり視角4分の曲線から Dynamic な状態における未知の実地視作業を見るのに必要な明るさが求められるわけである。

第11図 実地視作業に必要な明るさを求める基礎曲線、
supra-threshold Visibility Factor 15, 5 APS,
最大精度99%としたもの。

第11図は直径視角4分の標準視標につき5 APS の視作業を行なった場合、最大精度として99% accuracy level の域値をとった曲線で supra-threshold visibility factor を 15 としたものである。この曲線から実地視作業に必要な明るさを読みとることができる。

そこで3名の被検者により56種類の実地視作業について、視角4分の標準視標を用いて視作業定量機により測定を行なっている。その値は平均値であるが個人差は殆んど見られなかった。

6. 56種の実地視作業に対する推奨照度

56種の実地視作業に対する推奨照度を示している。その結果、必要輝度 (foot lambert) から作業の程度を五つの段階に分けた。

(foot lambert)

- A. Easy Task (容易な作業) 18 未満
- B. Ordinary Task (通常の作業) 18~42
- C. Difficult Task (困難な作業) 42~120
- D. Very Difficult Task (非常に困難な作業) 120~420
- E. Most Difficult Task (もっとも困難な作業)

420 以上

第1表は通常の視作業を5 APS と見て各視作業の5 APS の場合につき、作業の難しさと分類して必要な輝度、反射率、必要な照度を示している。なお supra-threshold visibility Factor を 15, 99% accuracy の最大精度をとってある。本稿の終りに新照度表の原文を掲げご参考にする。

第1表 56種実地作業の分類

作業番号	作業の記述	必要な輝度 (foot-lambert)	反射率	必要な照度 (foot-candle)
A. 容易な作業				
(23)	青いサージの布に明るい縫いつけ	.09	.018	5.05
(15)	青いサージの布に白いチョークの印し	.20	.020	10.4
(16)	暗い青の布の小さな破れ	.30	.017	17.8
(12)	暗い青の複写原紙 (透明プラスチックのふちとり)	.39	.11	3.54
(7)	12ポイント texttype	.42	.70	.60
(9)	タイプ (カーボン複写でないもの)			
	よいリボン	.60	.62	.97
(6)	10ポイント texttype	.66	.70	.94
(17)	黒い布の灰色の線状の破れ	.66	.024	27.5
(5)	8ポイント texttype	.79	.70	1.13
(33)	紡織機のボビンの切れた黒糸(30°照明)	.93	.079	11.8
(1)	インク筆記試料, 1人の六年級生徒	1.05	.76	1.38
(3)	8ポイント・ボドニタイプ	1.31	.70	1.87
(4)	6ポイント・ボドニタイプ	2.08	.70	2.98
(30)	値段票, インク	2.36	.76	3.10
(36)	Tight sound edge knot, 16 フィートから見る。	2.46	.19	12.9
(14)	青写真の上に重なるトレーシング ペーパーに2号鉛筆	3.88	.59	6.58
(31)	紡織機のボビンの切れた白い毛糸	4.17	.66	6.32
(22)	灰色の布の白いチョーク	6.92	.33	21.0
(24)	模様糸, 男物絹およびウールの衣類	7.24	.22	32.9
(18)	布色の布のかかった斑点	7.41	.10	74.1
(47)	新しいマイクロメーター, エッチした	7.41	(鏡面)	
(27)	模様糸, 白いハンカチ	8.97	.91	9.86
(35)	Ship defect, 16フィートから見る。	13.5	.19	71.
B. 通常の作業				
(41)	Small skip defect 30インチ から見る	35.6	.19	187.
C. 困難な作業				
(2)	2号鉛筆筆記資料, 6年級31人のク ラスのもっとも悪い12人	47.8	.76	63.
(21)	明るい茶色のツードのオレンジ 色のチョーク	47.9	.18	266.
(32)	紡織機のボビンの破れた黒糸, 30°照明	52.5	.018	2920.
(25)	絹の暗い茶色のはみ出た糸	58.9	.035	1680.
(40)	小さな seasoning check 30インチから見る	60.3	.19	317.
(8)	3号鉛筆筆記資料	60.5	.79	76.5
(11)	タイプ (5枚目のカーボン複写)	70.7	.53	133.
(37)	Bark wave, 16フィートから見る。	72.4	.19	381.
(43)	布の茶色の色差	100.	.12	870.
D. 非常に困難な作業				
(48)	古いマイクロメーター, 数字の 上の鏡面反射	148.	(鏡面)	
(29)	値段票, 鉛筆	151.	.63	241.
(42)	穀粒, 30インチから見る, 鏡 面反射なし	195.	.19	1030.
(13)	thermobax 複写, 質の悪いもの	371.	.63	589.

(34) 紡織機のボビンの切れた白糸, 30° 照明	380.	.78	487.
<u>E. もっとも困難な作業</u>			
(26) 絹の灰青色のはみでた糸	447.	.46	9650.
(45) Unproofed type (植字)	447.	(鏡面)	
(46) パーニャ・キャリバー, エッチ してない.	631.	(鏡面)	
(28) ポケットのぬいつけ, タン色の スカート	1000.	.53	1890.
(39) 穀粒, 16フィートから見る	1230.	.19	6470.
(10) タイプ (カーボン複写でないもの), ひどく悪いリボン	1950.	.62	3140.
(19) 茶色の絹に茶色のぬいつけ, 垂 直のぬいつけ	>3000.	.12	>10,000.
(20) 灰色の絹に灰色のぬいつけ, 水 平のぬいつけ	>3000.	.76	>10,000.
(38) 小さな朽ちた点, 16フィート から見る.	>3000.	.19	>10,000.
(44) 校正植字	>3000.	(鏡面)	
(49) 青写真の白線, トレーシング ペーパーを重ねる.	>3000.	.59	5090.
(50) 茶色の絹ツードに茶色の糸の ぬいつけ	>3000.	.12	>10,000.
(51) タン色の布に白いチョーク	>3000.	.24	>10,000.
(52) 白いハンカチのふち取りのきず	>3000.	.91	3,360.
(53) Seasoning check, 16フィ ートより見る.	>3000.	.19	>10,000.
(54) 灰色の布の茶色のしみ	>3000.	.12	>10,000.
(55) 赤いネクタイの茶色の点	>3000.	.84	>10,000.
(56) タン色のネクタイの茶色の点	>3000.	.176	>10,000.

新しい照度表

照明の質と量に対する勧告の委員会の11人の委員はまた、おもな応用委員会の委員長であるから、報告No. 1の勧告を履行し、適当な照度の勧告の各委員会による発展に対して、情報と主導性をあたえる立場にある。Blackwellの研究データが示され、指針として R.Q.Q. 報告ができるとすぐいろいろの委員会が同時に召集された。これらの委員会は、Blackwell が評価した実地作業を研究し、それぞれの分野のいろいろの領域に対して勧告される値のリストをつくることを試みた。それぞれの活動に応用できる Blackwell の測定した作業のないこ

とがしばしばあった。しかし測定された作業の相対的な困難さを評価し、直面した作業と比較することによって、勧告水準を得ることができた。これらの水準は各応用委員会の委員により投票が行われ、多数決により承認が会議 (Council) に求められた。

照明学会技術事務局 (Technical Office of I.E.S.) はいろいろの分野における類似した配置に対して値を関連させるように援助した。これらの表が、技術委員会で「勧告の実際 (Recommended Practice)」の改訂の際に研究され、また ILLUMINATING ENGINEERING の読者が研究するので、更に各分野の関連と一致性についての改善が可能である。すべての勧告水準は Blackwell データの抽出と、実地に見出される作業の範囲と呈供された試料作業に対して Blackwell の得た値と実際にこれらの計画水準を実現する能力を合同委員会で総合した結果得られた。もちろん、実験と判断にはいろいろあり、あるものは実験結果から高い照度勧告を示し、あるものは低い値を示した。

これらの新しい勧告は、実施に対する反響はいろいろあることが予想される。あるものは高過ぎると感るじであろうし、あるものは、Beackwell の評価に示されるように要求に対して基本的であることを承認するであろう。いまだで新しい水準が導入されたときいつもそうであったように、この新しい勧告は間もなく広く承認されるようになることが期待される。なぜなら商工業および家庭における見方の真の要求に適合するものであるからである。

(注) 本稿は照度調査委員会小委員会で、4回に亘り報告検討されたものの抄録である。原著は H.R. Blackwell 博士より本委員会に送付された1958年3月 IERI のシンポジウムに報告された記録によるものであるが、同種の論文が I.E. 1958 (Aug) に掲載されている。

	Currently Recommended Illumination* Footcandles		Currently Recommended Illumination* Footcandles
AIRPLANE MANUFACTURING			
Stock parts		Fine	500
Production	100	Extra Fine	1000
Inspection	200**		
AUTOMOBILE MANUFACTURING			
Parts manufacturing		Frame assembly	50
Drilling, riveting and screw fastening	70	Chassis assembly line	100
Spray booths	100	Final assembly and inspection line	200**
Sheet aluminum layout and template work; shaping and smoothing of small parts for fuselage; wing sections, cowl- ing, etc.	100	Body manufacturing	
Welding		Parts	70
General illumination	50	Assembly	100
Supplementary illumination	1000	Finishing and inspecting	200**
Subassembly			
Landing gear, fuselage, wing sections, cowl- ing and other large units	100	BAKERIES	
Final assembly		Mixing room	50
Placing of motors, propellers, wing sections and landing gear	100	Face of shelves (vertical illumination)	30
Inspection of assembled ship and its equipment ..	100	Inside of mixing bowl (vertical mixers)	50
Machine tool repairs	100	Fermentation room	30
AIRPLANE HANGARS			
Repair service only	100	Make-up room	
ASSEMBLY			
Rough easy seeing	30	Bread	30
Rough difficult seeing	50	Sweet yeast raised products	50
Medium	100	Proofing Room	30
		Oven room	30
		Fillings and other ingredients	50
		Decorating and icing	
		Mechanical	50
		Hand	100
		Scales and thermometers	50
		Wrapping room	30

	Currently Recommended Illumination* Footcandles		
BOOK BINDING		CENTRAL STATION OUTDOOR LOCATIONS	
Folding, assembling, pasting, etc.	70	Catwalks	2.0
Cutting, punching and stitching	70	Cinder dumps	0.1
Embossing and inspection	200**	Coal unloading	
		(a) Dock (loading or unloading zone)	5.0
		(b) Barge storage area	0.5
		(c) Car dumper	0.5*
		(d) Tipple	5.0
		Coal storage area	0.1
		Conveyors	2.0
		Entrances	
		Generating or service building	
		(a) Main	10.0
		(b) Secondary	2.0
		Gate house	
		(a) Pedestrian entrance	10.0
		(b) Conveyor entrance	5.0*
		Fence	0.2
		Fuel oil delivery headers	5.0
		Oil storage tanks	1.0
		Open yard	0.2
		Platforms — boiler, turbine deck	5.0
		Roadway	
		(a) Between or along buildings	1.0
		(b) Not bordered by buildings	0.5
		Substation	
		(a) General horizontal	2.0
		(b) Specific vertical (on disconnects)	2.0
		CHEMICAL WORKS	
		Hand furnaces, boiling tanks, stationary driers, stationary and gravity crystallizers	30
		Mechanical furnaces, generators and stills, me- chanical driers, evaporators, filtration, me- chanical crystallizers, bleaching	30
		Tanks for cooking, extractors, percolators, nitra- tors, electrolytic cells	30
		CLAY PRODUCTS AND CEMENTS	
		Grinding, filter presses, kiln rooms	30
		Molding, pressing, cleaning and trimming	30
		Enameling	100
		Color and glazing — rough work	100
		Color and glazing — fine work	300**
		CLEANING AND PRESSING INDUSTRY	
		Checking and sorting	50
		Dry and wet cleaning and steaming	50
		Inspection and spotting	500**
		Pressing	
		Machine	150
		Hand	150
		Repair and alteration	200**
		CLOTH PRODUCTS	
		Cloth inspection	2000**
		Cutting	300**
		Sewing	500**
		Pressing	300**
		COAL TIPPLES AND CLEANING PLANTS	
		Breaking, screening and cleaning areas	10
		Picking	300**
		DAIRY PRODUCTS	
		Fluid milk industry	
		Boiler room	30
		Bottle storage	30
		Bottle sorting	50
		Bottle washers	††
		Can washers	30
		Cooling equipment	30
		Filling: inspection	100
		Gages	50
		Laboratories	100
		Meter panels	50
		Pasteurizers	30
		Separators	30
		Storage refrigerator	30
		Tanks, vats	
		Light interiors	20
		Dark interiors	100
		Thermometer	50
		Weighing room	30
		Scales	70
		ELECTRICAL EQUIPMENT MANUFACTURING	
		Impregnating	50
		Insulating: coil winding	100
		Testing	100
		EXPLOSIVES	
		Hand furnaces, boiling tanks, stationary driers, stationary and gravity crystallizers	30
BREWERIES			
Brew house	30		
Boiling and keg washing	30		
Filling (bottles, cans, kegs)	50		
CANDY MAKING			
Box department	50		
Chocolate department			
Husking, winnowing, fat extraction, crush- ing and refining, feeding	50		
Bean cleaning and sorting, dipping, packing, wrapping	50		
Milling	100		
Cream making			
Mixing, cooking and molding	50		
Gum drops and jellied forms	50		
Hand decorating	100		
Hard candy			
Mixing, cooking and molding	50		
Die cutting and sorting	100		
Kiss making and wrapping	100		
CANNING AND PRESERVING			
Initial grading raw material samples	50		
Tomatoes	100		
Color grading (cutting rooms)	200**		
Preparation			
Preliminary sorting			
Apricots and peaches	50		
Tomatoes	100		
Olives	150		
Cutting and pitting	100		
Final sorting	100		
Canning			
Continuous belt canning	100		
Sink canning	100		
Hand packing	50		
Olives	100		
Examination of canned samples	200**		
Container handling			
Inspection	200**		
Can unscramblers	70		
Labeling and cartoning	30		
CENTRAL STATION INDOOR LOCATIONS			
Air-conditioning equipment, air preheater and fan floor, ash sluicing	10		
Auxiliaries, battery rooms, boiler feed pumps tanks, compressors and gauge area	20		
Boiler platforms	10		
Burner platform	20		
Cable room, circulator or pump bay	10		
Coal conveyor, crusher, feeder, scale areas, pul- verizer, fan area, transfer tower	10		
Condensers, deaerator floor, evaporator floor and heater floors	10		
Control rooms			
Vertical face of switchboards			
Simplex or section of duplex facing operator,			
Type A — Large centralized control room 66 inches above floor	50		
Type B — Ordinary control rooms at 66 inches above floor	30		
Section of duplex facing away from operator	30		
Bench boards (horizontal level)	50		
Area inside duplex switchboards	10		
Rear of all switchboard panels (vertical)	10		
Emergency lighting, all areas	3		
Hydrogen and carbon dioxide manifold area	20		
Chemical laboratory	50		
Precipitators	10		
Screen house	20		
Soot or slag blower platform	10		
Steam headers and throttles	10		
Switchgear power	20		
Telephone equipment room	20		
Tunnels or galleries, piping	10		
Turbine bay sub-basement	20		
Turbine room	30		
Visitor's gallery	20		
Water treating area	20		

EXPLOSIVES (continued)

Currently
Recommended
Illumination*
Footcandles

Mechanical furnaces, generators and stills, mechanical driers, evaporators, filtration, mechanical crystallizers 30
Tanks for cooking, extractors, percolators, nitro-
tors 30

EXTERIOR AREAS

Entrances
Active (pedestrian and/or conveyance) 5.0
Inactive (normally locked, infrequently used) 1.0
Vital locations or structures 5.0
Building surrounds 1.0
Active shipping area surrounds 5.0
Storage areas — active 20
Storage areas — inactive 1
Loading and unloading platforms 20

FLOUR MILLS

Rolling 50
Sifting 50
Purifying 50
Packing 30
Product control 100
Cleaning screens, man lifts, aiseways and walk-
ways, bin checking 30

FORGE SHOPS 50**FOUNDRIES**

Annealing (furnaces) 30
Cleaning 30
Core making (fine) 100
Core making (medium) 50
Grinding and chipping 100**
Inspection (fine) 500**
Inspection (medium) 100
Moulding (medium) 100
Moulding (large) 50
Pouring 50
Sorting 50
Cupola 20
Shakeout 30

GARAGES — AUTOMOBILE AND TRUCK

Service garages
Repairs 100
Active traffic areas 20
Parking garages
Entrance 50
Traffic lanes 10
Storage 5

GLASS WORKS

Mix and furnace rooms, pressing andlehr, glass
blowing machines 30
Grinding, cutting glass to size, silvering 50
Fine grinding, polishing, beveling 100
Inspection, etching and decorating 200**

GLOVE MANUFACTURING

Pressing 300**
Knitting 100
Sorting 100
Cutting 300**
Sewing and inspection 500**

HAT MANUFACTURING

Dyeing, stiffening, braiding, cleaning and refining 100
Forming, sizing, pouncing, flanging, finishing and
ironing 200**
Sewing 500**

INSPECTION

Ordinary 50
Difficult 100
Highly difficult 200**
Very difficult 500**
Most difficult 1000**

IRON AND STEEL MANUFACTURING

Open hearth
Stock yard 10
Charging floor 20
Pouring slide
Slag pits 20
Control platforms 30
Mold yard 5
Hot top 30
Hot top storage 10
Checker cellar 10
Buggy and door repair 30
Stripping yard 20

Scrap stockyard 10
Mixer building 30
Calcining building 10
Skull cracker 10
Cinder dump 0.1

Rolling mills

Blooming, slabbing, hot strip, hot sheet 30
Cold strip, plate 30
Pipe, rod, tube, wire drawing 50
Merchant and sheared plate 30
Tin plate mills
Tinning and galvanizing 50
Cold strip rolling 50
Motor room, machine room 30
Inspection
Blackplate, bloom, billet chipping 100
Tinplate, other bright surfaces 100†

LAUNDRIES

Washing 30
Flatwork ironing, weighing, listing and marking 50
Machine and press finishing, sorting 70
Fine hand ironing 100

LEATHER MANUFACTURING

Cleaning, tanning and stretching, vats 30
Cutting, fleshing and stuffing 50
Finishing and searling 100

LEATHER WORKING

Pressing, winding and glazing 200
Grading, matching, cutting, searling, sewing 300

LOCKER ROOMS 20**MACHINE SHOPS**

Rough bench and machine work 50
Medium bench and machine work, ordinary auto-
matic machines, rough grinding, medium
buffing and polishing 100
Fine bench and machine work, fine automatic
machines, medium grinding, fine buffing and
polishing 500**
Extra fine bench and machine work, grinding —
fine work 1000**

MATERIALS HANDLING

Wrapping, packing, labeling 50
Picking stock, classifying 30
Loading, trucking 20
Inside truck bodies and freight cars 10

MEAT PACKING

Slaughtering 30
Cleaning, cutting, cooking, grinding, canning,
packing 100

**PACKING AND BOXING (SEE MATERIALS
HANDLING)****PAINT MANUFACTURING**

General 30
Comparing mix and standard (see Color Match-
ing) 200†

PAINT SHOPS

Dipping, simple spraying, firing 50
Rubbing, ordinary hand painting and finishing art,
stencil and special spraying 50
Fine hand painting and finishing 100
Extra fine hand painting and finishing (auto-
mobile bodies, piano cases, etc.) 300**

PAPER BOX MANUFACTURING

General manufacturing area 50

PAPER MANUFACTURING

Beaters, grinding, calendering 30
Finishing, cutting, trimming, paper-making ma-
chines 50
Hand counting, wet end of paper machine 70
Paper machine reel, paper inspection and labora-
tories 100
Rewinder 150

PLATING 30**POLISHING AND BURNISHING** 100**PRINTING INDUSTRIES**

Type foundries
Matrix making, dressing type 100
Font assembly — sorting 50
Hand casting 50
Machine casting 50
Printing plants
Color inspection and appraisal 200**
Machine composition 100
Composing room 100
Presses 70

PRINTING INDUSTRY (continued)

Currently
Recommended
Illumination*
Footcandles

Imposing stones	150
Proof reading	150
Electrotyping	
Molding, finishing, leveling molds, routing, trimming	100
Blocking, tinning	50
Electroplating, washing, backing	50
Photo engraving	
Etching, staging	50
Blocking	50
Routing, finishing, proofing	100
Tint laying	100
Masking	100

RECEIVING AND SHIPPING (SEE MATERIALS HANDLING)

RUBBER TIRE AND TUBE MANUFACTURING

Stock preparation	
Banbury, plasticating, milling	30
Calendering	50
Fabric preparation	
Stock cutting, bead building	50
Tube tubing machines	50
Tread tubing machines	50
Tire building	
Solid tire	30
Pneumatic tire	50
Curing department	
Tube curing, casing curing	70
Final inspection	
Tube, casing	200**
Wrapping	50

RUBBER GOODS — MECHANICAL

Stock preparation	
Plasticating, milling, Banbury	30
Calendering	50
Fabric preparation	
Stock cutting, hose looms	50
Molded products and curing	50
Extruded products	50
Inspection	200**

SHEET METAL WORKS

Miscellaneous machines, ordinary bench work	50
Presses, shears, stamps, spinning, medium bench work	50
Punches	50
Tin plate inspection, galvanized	200††
Scribing	200††

SHIP YARDS

General	5
Ways	10
Fabrication areas	30

SHOE MANUFACTURING (LEATHER)

Cutting and stitching	
Cutting tables	300**
Marking, buttonholing, skiving, sorting, vamping and counting	300**
Stitching	
Dark materials	300**
Making and finishing	
Nailers, sole layers, welt beaters and scarf- ers, trimmers, welters, lasters, edge setters, sluggers, randers, wheelers, treers, cleaning, spraying, buffing, polish- ing, embossing	200

SHOE MANUFACTURING (RUBBER)

Washing, coating, mill run compounding	30
Varnishing, vulcanizing, calendering, upper and sole cutting	50
Sole rolling, lining, making and finishing processes	100

SOAP MANUFACTURING

Kettle houses, cutting, soap chip and powder	30
Stamping, wrapping and packing, filling and packing soap powder	50

STAIRWAYS, WASHROOMS AND OTHER

SERVICE AREAS	20
---------------------	----

STONE CRUSHING AND SCREENING

Belt conveyor tubes, main line shafting spaces, chute rooms inside of bins	10
Primary breaker room, auxiliary breakers under bins	10
Screens	20

STORAGE ROOMS OR WAREHOUSES

Inactive	5
Active	
Rough bulky	10
Medium	20
Fine	50

STRUCTURAL STEEL FABRICATION

SUGAR REFINING

Grading	50
Color inspection	200

TESTING

General	50
Extra fine instruments, scales, etc.	200**

TEXTILE MILLS (COTTON)

Opening, mixing, picking	30
Carding and drawing	50
Slubbing, roving, spinning and spooling	50
Beaming and slashing on comb	
Grey goods	50
Denims	50
Inspection	
Grey goods (hand turning)	100
Denims (rapidly moving)	500**
Automatic tying-in	150**
Drawing-in by hand	200**
Weaving	100

TEXTILE MILLS (SILK AND SYNTHETICS)

Manufacturing	
Soaking, fugitive tinting, and conditioning or setting of twist	30
Winding, twisting, rewinding, and coning, quill- ing, slashing	
Light thread	50
Dark thread	200
Warping (silk or cotton system) on creel, on running ends, on reel, on beam, on warp at beaming	100
Drawing-in	
On heddles	200**
On reed	200**
Weaving	100

TEXTILE MILLS (WOOLEN AND WORSTED)

Opening, blending, picking	30
Grading	100**
Carding, combing, recombining, gilling	50
Drawing (white)	50
Drawing (colored)	100
Spinning (frame) (white)	50
Spinning (frame) (colored)	100
Spinning (mule) (white)	50
Spinning (mule) (colored)	100
Twisting (white)	50
Winding (white)	30
Winding (colored)	50
Warping (white)	50
Warping (white) (at reed)	100
Warping (colored)	100
Warping (colored) (at reed)	300**
Weaving (white)	100
Weaving (colored)	200

Notes on Industrial Areas

*Minimum on the task at any time.

**Obtained with a combination of general lighting plus specialized supplementary lighting. Care should be taken to keep within the recommended brightness ratios. These seeing tasks generally involve the discrimination of fine detail for long periods of time and under conditions of poor contrast. To provide the required illumination, a combination of the general lighting indicated plus specialized supplementary lighting is necessary. The design and installation of the combination system must not only provide a sufficient amount of light, but also the proper direction of light, diffusion, and eye protection. As far as possible it should eliminate direct and reflected glare as well as objectionable shadows.

†The specular surface of the material may necessitate special consideration in selection and placement of lighting equipment, or orientation of the work.

††Special lighting such that (1) the luminous area shall be large enough to cover the surface which is being inspected and (2) the brightness be within the limits necessary to obtain comfortable contrast conditions. This involves the use of sources of large area and relatively low brightness in which the source brightness is the principal factor rather than the footcandles produced at a given point.

TEXTILE MILLS (continued)

	Currently Recommended Illumination* Footcandles
Grey goods room	
Burling	150**
Sewing	300**
Folding	70
Wet finishing	
Fulling	50
Scouring	50
Crabbing	50
Drying	50
Dyeing	100**
Dry finishing	
Napping	70
Shearing	100**
Conditioning	70
Pressing	70

Inspecting (perching)	2000**
Folding	70
TOBACCO PRODUCTS	
Drying, stripping, general	30
Grading and sorting	200**
UPHOLSTERING — AUTOMOBILE, COACH FURNITURE	100
WAREHOUSE (see Storage)	
WELDING	
General illumination	50
Precision manual arc welding	1000**
WOODWORKING	
Rough sawing and bench work	30
Sizing, planing, rough sanding, medium machine and bench work, glueing, veneering, cooperage	50
Fine bench and machine work, fine sanding and finishing	100

INSTITUTIONS

(Notes for this section are on page 430)

ART GALLERIES

General	30
On paintings (supplementary)	30
On statuary and other displays	100

(1) Dark paintings with fine detail should have 2 to 3 times higher illumination.

(2) In some cases, much more than 100 footcandles is necessary to bring out the beauty of statuary.

HOSPITALS

Anesthetizing and preparation room	30
Auditorium	
Assembly	15
Exhibition	30
Autopsy and morgue	
Autopsy room	100
Autopsy table	2500
Morgue, general	20
Central sterile supply	
General	30
Needle sharpening	150
Corridor	
General	10
Operating and delivery suites and labora- tories	20
Cystoscopic room	
General	100
Cystoscopic table	2500
Dental suite	
Waiting room	
General	15
Reading	30
Operator, general	70
Instrument cabinet	150
Dental chair	1000
Laboratory, bench	100
Recovery room	5
Dining room (see Restaurants)	
Electroencephalographic suite	
Office	100
Workroom	30
Patients' room	30
Emergency room	
General	100
Local	2000
EKG, BMR and Specimen room	
General	20
Specimen table (supplementary)	50
Examination and treatment room	
General	50
Examining table	100
Eye, ear, nose and throat suite	
Dark room	10
Eye examination and treatment room	20
Ear, nose and throat room	20
Exits, at floor	5

Flower room	10
Formula room	30
Fracture room	
General	50
Fracture table	200
Kitchen	
Central	70
Floor, kitchen and pantry	70
Dishwashing	30
Laboratories	
Assay rooms	30
Work tables	50
Close work	100
Laundry	
General	30
Pressers and ironers	70
Sorting	70
Libraries	70
Linen closet	10
Locker rooms	20
Lobby	30
Lounge rooms	30
Maintenance shop	
General	30
Work benches	100
Paint storage	10
Medical records room	100
Nurses' station	
General	20
Desk and charts	50
Medicine room counter	100
Nurses' workroom	30
Nurseries	
General	10
Examination table	70
Play room, pediatric	30
Obstetrical	
Clean-up room	30
Scrub-up room	30
Labor room	20
Delivery room, general	100
Delivery table	2500
Offices (See Offices)	
Parking lot	5
Power plant	
Boiler room	10
Machine room	20
Switchboard room	30
Transformer room	10
Pharmacy	
General	30
Work table	100
Active storage	30
Alcohol vault	10
Private rooms and wards	
General	10
Reading	30
Psychiatric disturbed patients' areas	10
Radioisotope facilities	
Radiochemical laboratory	30
Up-take measuring room	20
Examination table	50

HOSPITALS (continued)

	Currently Recommended Illumination* Footcandles
Retiring room	10
Sewing room	
General	20
Work area	100
Solariums	20
Stairways	20
Storage, central	
General	15
Office	70
Surgery	
Instrument and sterile supply room	30
Clean-up room (instruments)	100
Scrub-up room	30
Operating room, general	100
Operating table	2500
Recovery room	30
Therapy	
Physical	20
Occupational	30
Toilets	10
Utility room	20
Waiting room	
General	15
Reading	30
X-ray room and facilities	
Radiography and fluoroscopy	10
Deep and superficial therapy	10
Darkroom	10
Waiting room, general	15
Waiting room, reading	30
Viewing room	30
Filing room, developed films	30
Storage, undeveloped films	10

HOTELS

Auditoriums	
Assembly only	15
Exhibitions	30
Dancing	5
Bars and cocktail lounges (see Restaurants)	
Bathrooms	
Mirror†	30
General	10
Bedrooms	
Reading (books, magazines, newspapers)	30
Inkwriting**	30
Make-up††	30
General	10
Corridors, elevators and stairs	20
Dining areas (see Restaurants)	
Entrance foyer	30
Front office	50
Kitchen (see Restaurants)	
Laundry	
Washing	30
Flat work ironing	50
Machine and press finishing	70
Linen room	
Sewing	100
General	20
Lobby	
General lighting	10
Reading and working areas	30
Marquee	
Dark surroundings	30
Bright surroundings	50
Offices	
Accounting	150
General	100
Reception	30
Power plant	
Boiler room	10
Equipment room	20
Storerooms	10
Work shops (See Machine Shops and Woodwork- ing, under Industrial Areas Section)	

MUSEUMS (SEE ART GALLERIES)

PROFESSIONAL OFFICES (SEE HOSPITALS)

RESTAURANTS, lunch rooms, cafeterias

Dining Areas	
Cashier	50
Intimate type	
Light environment	10
Subdued environment	3

Notes on Institutions

*Minimum on the task at all times.

**Pencil handwriting, reading of reproductions and poor copies require 70 footcandles.

†This may be done in the bathrooms, but if a dressing table is provided, local lighting should provide the level recommended.

††Including street and nearby establishments.

‡For close inspection, 50 footcandles.

For cleaning	20
Leisure type	
Light environment	30
Subdued environment	15
Quick service type	
Bright surroundings††	100
Normal surroundings††	50
Food displays—twice the general levels but not under	50
Kitchen, commercial	
Inspection, checking and pricing	70
Other areas	30

OFFICES

	Currently Recommended Illumination* Footcandles
OFFICES	
Cartography, designing, detailed drafting	200
Accounting, auditing, tabulating, bookkeeping, business machine operation, reading poor re- productions, rough layout drafting	150
Regular office work, reading good reproductions, reading or transcribing handwriting in hard pencil or on poor paper, active filing, index references, mail sorting	100
Reading or transcribing handwriting in ink or medium pencil on good quality paper, inter- mittent filing	70
Reading high contrast or well-printed material, tasks and areas not involving critical or pro- longed seeing such as conferring, interview- ing, inactive files and washrooms	30
Corridors, elevators, escalators, stairways	20
	(or not less than 1/2 level in adja- cent areas)

BANKS

Lobby	
General	50
Writing areas	70
Tellers' stations	150
Posting and keypunch	150
Regular office work	100

DEPOTS, TERMINALS AND STATIONS

Waiting room	30
Ticket offices	
General	100
Ticket rack and counters	100
Rest room and smoking room	30
Baggage checking	50
Storage	20
Concourse	10
Platforms	20
Toilets and washrooms	30

DRAFTING ROOMS (SEE OFFICES)

MUNICIPAL BUILDINGS (Fire and Police)

Office work, corridors, elevators, stairways, wash- rooms (see Offices)	
Police	
Identification records	150
Jail cells and interrogation rooms	30
Fire Hall	
Dormitory	20
Recreation room	30
Wagon room	30

	Currently Recommended Illumination* Footcandles
POST OFFICES	
Lobby, on tables	30
Sorting, mailing, etc.	100
Storage	20
Files (see Offices)	
Corridors and stairways	20

*Minimum on the task at all times.

STORES

	Currently Recommended Illumination* Footcandles
Show windows	
Daytime lighting	
General	200
Feature	1000
Nighttime lighting	
Main business districts — highly competitive	
General	200
Feature	1000
Secondary business districts or small towns	
General	100
Feature	500
Open-front stores (see Display lighting under Store interiors)	
Store interiors	
Circulation areas	30
Merchandising areas	
Service	100
Self-service	200
Showcases and wall cases	
Service	200
Self-service	500
Feature displays	
Service	500
Self-service	1000
Stockrooms	30

(1) Above values are illumination on the merchandise on display or being appraised. The plane in which lighting is important may vary from horizontal to vertical.

(2) Specific appraisal areas involving difficult seeing may be lighted to substantially higher levels.

(3) Color rendition of fluorescent lamps is important. Incandescent and fluorescent usually are combined for best appearance of merchandise.

(4) Illumination may often be made non-uniform to tie in with merchandising layout.

*Minimum on the task at all times.

RESIDENCES

	Currently Recommended Illumination* Footcandles
SPECIFIC VISUAL TASKS*	
Table games	30
Kitchen activities	
Sink	70
Range and work surfaces	50
Laundry, trays, ironing board, ironer	50
Reading and writing, including studying	
Books, magazines, newspapers	30
Handwriting, reproduction and poor copies ..	70
Desks, study	70
Reading music scores	
Simple scores	30

Advanced scores	70
(When score is substandard size, and notations are printed on the lines, 150 footcandles or more are needed.)	
Sewing	
Dark fabrics (fine detail, low contrast)	200
Prolonged periods (light to medium fabrics) ..	100
Occasional periods (light fabrics)	50
Occasional periods (coarse thread, large stitches, high contrast thread to fabric) ..	30
Shaving, make-up, grooming: on the face at mirror locations	50
Work shop, bench work	70
GENERAL LIGHTING	
Entrances, hallways, stairways, stair landings	10†
Living room, dining room, bedroom, family room, sun room, library, game or recreation room ..	10†
Kitchen, laundry, bathroom	30

*Minimum on the task at all times.

**Brightness of visual task must be related to background brightness.

†General lighting for these areas need not be uniform in character.

MARINE TRANSPORTATION

	Currently Recommended Illumination* Footcandles
LIVING AREAS	
Staterooms	
Crew	5**
Officers	5**
Passengers	5**
Berth, on reading plane	15
Mirrors, at face	50
Baths	
Crew	5
Public	5
Officers	5
Passengers	5
Mirrors, at face	50
Passageways	5
Stair foyers, passenger	10
Stairs	
Passenger	10
Crew	5
Entrance, passenger	10†
Lounges, passenger and officers	10**†
Recreation rooms, crew	20
On tables	30
Dining room, passengers	10†
Mess room, officers and crew	10
On tables	15
Libraries	10
For reading	30
Smoking rooms	5**†
Enclosed promenades, along inboard bulkhead for reading	10
Barber shop and beauty parlor	20
On subject	50
Cocktail lounges	5†
Bars	5†
Ball rooms	5†
Swimming pools, indoor beaches	10

(Also underwater lights and sun lamps)

Shopping areas	20**
Theatres	
During show	0.1
Intermission	5
Gymnasiums	20
Hospital	
Operating room	50**
Dental room	30**
Dispensary	30**
Wards	5**
Doctor's office	20**
Waiting room	10**†
Radio room, passenger foyer	10**†
Passenger counter, purser's office	20

		Currently Recommended Illumination* Footcandles	OPERATING AREAS	
NAVIGATING AREAS			Engine rooms (working areas)	10**
Wheelhouse (not used underway)	5		Boiler rooms (working areas)	10**
Chart room	10		Fan rooms	5
On chart table	50		Motor generator rooms (cargo handling)	5
Radar room	5		Generator and switchboard rooms	10
Gyro room	5		Windlass rooms	5
Radio room	10**		Switchboards, vertical illumination:	
Ship's offices	20		At top	20
On desks and work tables	50		Three feet above deck	19
For bookkeeping and auditing	50		Steering gear room	5
Log room	10		Pump room	1
On desk	50		Gauge and control boards (vertical illumination)	
SERVICE AREAS			On gauges	30
Galley	20**		Shaft alley	3
Laundry	15**		Dry cargo holds (permanent fixture)	1**
Pantry	15**		Refrigerated cargo loading and unloading	3**
Sculleries	15**		Work shops	20
Food preparation	20**		On work	50
Food storage (non-refrigeration)	5		Cargo hatches	
Refrigerated spaces (ship's stores)	5		Over hatch area	5
Butcher shop	15**		Adjacent deck area	3
Print shop	30**		*Minimum on the task at all times.	
Tailor shop	50**		**Supplementary lighting should be provided in this space to produce the higher levels of lighting required for specific seeing tasks involved.	
Post offices	20**		†In public areas such as lounges, ballrooms, bars, smoking rooms and dining rooms, the footcandle values may vary widely, depending upon the atmosphere desired, the decorative scheme and the use made of the room.	
Lockers	3		‡The installation should be such that the level of illumination can be increased to at least 40 footcandles for daytime embarkation.	
Telephone exchange	10**			
Store rooms	5			

今 や 知 っ て い る

I. E. S. 会長 KIRK M REID

個々の I. E. S. 会員、学会全般、および特に賛助会員は以上に発表された照明に関する研究発表に誇りが持てる。彼等の知識を求める熱心さ、先見の明——および数千ドルの投資により照度勧告の立派な科学的基礎が得られたことは計り知れないものである。われわれの委員会を長い間はばんでいた一つのギャップが充された。今やわれわれはいかなる視作業に対しても、照度をきめるのにどれだけの量の光が目標であるかを、合理的な精度でいかに評価したらよいか知っているのである。

今、報告された研究項目の結末はきたるべき研究結果（あるものは間もなく得られる）に対する待望を刺激してくれる。この研究を行う保護作用をした照明工学研究協会 (IERI) には現在実施中の多くの研究項目がある。事実、Blackwell による量の評価の研究は照明の「量」に関する多面的研究の一部に過ぎない。現在進行中の他の研究には「質」に関するもの、照明の正確な予言のための計算機および街路照明に関するものがある。他にわれわれが必要とする解答を先見していくつかをあげてみる。

・年寄の目に必要な量

- ・視覚異常者に必要な量
- ・眼の動きの効果 (Ocular motor effect) ——照度水準が変化したとき、目はいかに焦点を結ぶか
- ・不快な眩光
- ・明るさの比
- ・鏡面反射
- ・照度の値の計算
- ・照明された道路の可視度の評価

われわれはすべて個々の会員として I E R I の研究項目に関心がある。照明学会 (I. E. S.) の I. E. R. I. の研究項目に対する過去および現在の投資は今日、25万ドルを超える。これは決して巨大な額ではないが、可成の額である。これらの研究が現存の大学の設備と高度に教育された大学の人材を利用したことは、その価値を何倍にも増した。われわれの寄与は幸運にもそのようにして数倍された。

I. E. R. I. 研究の成果に関して——人類に対して照明ができることを広げることに分担し、それを豊かにし、保護し、重荷を軽くしてやったことに對しわれわれは喜びと誇りを持つのである。