講

Metallographical Study on Galvanised Steel.

演

Y. Taji,

Constructor-Lieutenant, I. J. N. Member.

亞鉛鍍鋼の組織學的研究外一篇

To galvanise steel materials as a protection from its corrosion is a popular practice in dockyards as well as in iron firms. Particularly for ships of extremely light scantlings as destroyers it is the essential thing for their protection from corrosion.

The practice of galvanising steel is a very simple and well-known matter, but with regard to the metallographical structure and its effect on the strength, there have been few publications dealing with the matter in detail, although it is already known that the galvanised iron has in general two layers of the coating near its surface, i. e., iron-zinc alloy and zinc itself.

I. IRON-ZINC ALLOY.

The chemical properties of the iron-zinc compounds or the alloy are not very popularly known, even in technical circles. The only rigorous paper which deals with the problem very clearly will be that of Mr. Vegesack*, so far as the author is aware. The existence of a chemical compound of iron and zinc has been proved by several investigators by analysing the deposit on the bottom of a zinc-melting bath made of iron.

二四(横)

* See Zeitschrift für Anorganische Chemie. Band LII. P. 30, 1907, "Über Zinc-Thallium- und Zink-Eisenlegierungen" Von A. V. Vegesack.

These compounds were of 5 % to 6.24 % of iron, 99.76 % to 93.01 % of Zinc, with a very small quantity of carbon or some other impurities. From Vegesack's investigation we know

(1) The alloy of iron and zinc with 11 to 24 % of Fe. consists from some unknown crystals and liquid in a temperature above 777°C . At 777°C the crystals and liquid form a compound FeZn_3 .

(2) The properties of alloy with 0.7 to 11 % Fe are rather complicated.

(a) With Fe above 3.5 %, it generally consists from FeZn_3 and liquid at a temperature between 662°C and 777°C . At 662°C , they will form a compound FeZn_7 .

(b) At a temperature between 422°C and 662° , it consists generally from FeZn_3 and FeZn_7 , or their mixed crystals.

(c) At 422° , the alloy with 7.3 % of Fe constructs a certain saturated mixed crystal called 'n.' consisting from FeZn_3 and FeZn_7 .

At about 275° , the alloy with 0.7 % of Fe forms another saturated mixed crystal 'm,' having different disposition of FeZn_3 and FeZn_7 .

The mixed crystal 'n' is a very hard and brittle material, but 'm' is only a little harder than pure zinc.

The solidification curve is given in Pl. IV. The microstructure of iron-zinc alloy is quite different from the ordinary zinc structure. Fig. 3 shows a typical structure of Fe-Zn Alloy with mixed crystals of 'm' and 'n.' This material is fairly brittle, so as we can easily break it by striking with a small hammer. The

micro-structure of zinc which I have used for the present experiment is shown in Fig. 4.

2. General construction of the Microstructure of Galvanised Steel.

A number of small mild steel blocks of cubical shape with sides about $1/2''$, taken from a rectangular rolled bar, were pickled by strong hydrochloric acid until their surfaces became quite clean and then were washed thoroughly by water.

After drying them perfectly, they were immersed in a molten-zinc bath whose temperature was nearly 650°C .

The typical structures of galvanised steel are shown in Figs. 1 and 2. It will be seen that it consists from three layers. "a" is the layer which is directly contact with the steel surface S. This is a very hard and brittle layer and its direction of crystallisation is always perpendicular to the steel surface. As I have mentioned already, even a deposit on the bottom of a melting bath which was used for so long a time, does not contain more than 6.5 % of iron, so that it will be evident that these layers will not possibly contain more than that quantity of iron. Comparing the structure of the first layer 'a' with those obtained by the chemical study on the iron-zinc compounds, it appears to be an iron-zinc alloy with about 5 % of iron.

This layer consists from a greater part of 'n' crystals and a smaller amount of 'm' crystals.

The cleavage line of the crystals is weakest in the direction perpendicular to the steel surface, so that this layer will separate into numerous parts by shock or strain. But as it is an altogether brittle material, they will be broken into several blocks as shown in Fig. 16.

譯

演

亞鉛鍍鋼の組織學的研究外一篇

二六(續)

The second layer 'b' is generally granular structure as conglomerate. It is evident that this layer is also iron-zinc alloy of less Fe contents. This layer appears to contain somewhat 2 % iron. It is not so hard or brittle as the layer 'a', so that it will not be broken easily by shock or strain. The greater part will be 'm' crystal and less amount of 'n' crystals will exist.

The structure of this layer is very similar to an iron-zinc alloy which is shown in Fig. 3. Sometimes this layer consists from numerous hexagonal grain structures of less iron contents which may be considered practically as 'm' crystals.

The third layer 'c' is zinc itself which generally has small grain structure as shown in Fig. 4.

Generally, the contact boundary of 'a' and 'b' layers is distinct, but 'b' structure will be gradually shaded off towards zinc.

3. The Effect of zinc for Galvanisation.

In order to investigate the alteration of the structure due to the duration of galvanisation, specimens were kept in the zinc bath from 15 minutes to 150 minutes. The general feature will be seen from Figs. 5-10.

In 15 minutes, the majority may be considered as 'm' crystals with a small amount of 'n' crystals, as shown in Fig. 5. But they will not lose the characteristic feature of the formation of layers, which I explained in the previous article. (See Fig. 6.)

Generally speaking, under 30 minutes, the formation of layers is not so perfect as shown in a typical case (Fig. 1.) The absorption of Fe from steel will not exceed more than 3 %, so that the first hard laminated structure of 'm' crystals is not greatly formed, but is only located along the steel surface.

At 45 minutes the formation of the typical structures is quite perfect, and the amount of absorption of Fe. from steel is evidently more than 5 %, as in Fig. 7 and 8.

The laminated hard layer 'a' sometimes will have the irregular broken structure when the surface of the steel is very rough, as it has more freedom for crystallisation, than the smooth fair surface where there is no space of escaping of zinc-alloy solution.

In some cases, however, this is partly due to high brittleness of this layer and they are often broken into pieces while polishing, as shown in Fig. 10.

After 60 minutes, the general feature of the layers is not materially altered, except in the increase of thickness of the iron-zinc alloy layers. But the special phenomena due to the long immersion is the penetration of zinc into steel as shown in Fig. 9. This phenomena happens sometimes even in a short time immersion, but it becomes very remarkable after 45 minutes.

This seems to happen by the decarburising effect of zinc as well as the existence of the weak decayed part of steel on the surface, accompanied by the natural defect or small inlet on the initial surface of steel.

One or two specimens were carefully filed to take off some of the thickness of the upper surface of steel. Then the penetration of zinc was practically nil.

Thus it may be considered that a certain amount of the penetration of zinc into steel will generally happen in the ordinary galvanising process.

4. Galvanised Steel Wires.

Owing to the extraordinary increase in the use of galvanised

steel wire, the study on the effect of galvanisation on its strength and its structure will not be of small importance. Particularly for the naval services, practically all steel wires are galvanised in order to avoid corrosion.

Generally speaking, there are two methods of galvanising steel wires. As these wires are generally hard drawn, the first method is to galvanise wires before they are drawn, and the second method is after drawing.

The construction of structure near the surface of wire is practically similar to the previous cases which I have already explained. Fig. 11 shows the structures of zinc and its iron alloy in the vicinity of the surface of the wire, which was galvanised after drawing. Fig. 13 shows the structure of the galvanised part of the wire which was galvanised before drawing. In this case it will be seen that the whole zinc-iron alloy and zinc layers are shifted gradually against the direction of drawing.

Figs. 14 and 15 show the structure of steel wire near the surface. We will see clearly the segregation of ferrite. By galvanising steel wires, the segregation of ferrite will occur more or less, firstly owing to high heating of steel, secondly by the decarburising effect of zinc.

Comparing this phenomena with the penetration of zinc into steel, we will find that this segregation is quite a different occurrence and will probably happen in higher carbon or some special steel. Referring to the two methods of galvanisation, the first is generally considered the better, as the wire is not heated in a zinc-bath after it is drawn, so that the reduction of strength due to reheating will possibly not occur.

The following results show a tensile and a torsional test. The torsional test was carried out by an Amsler's Torsion machine

and the tensile test by a 5-ton Buckton Machine.

講 (A) TENSILE TEST.

	1st. Method.	2nd. Method.
	Wire Galvanised before drawing.	Wire galvanised. after drawing.
Gauge length in ins.	3.99	4.96
Diameter in ins.	.128	.1295
Young's modulus, E. in lbs/sq. in.	21.15×10^6	24.5×10^6
Elastic limit in Tons/sq. in.	58	58.2
Ultimate strength in Tons/sq. in.	85	87.8
Percentage elongation.	2.88 %	5.76 %

(B) TORSIONAL TEST.

	Wire galvanised before drawing.	Wire galvanised after drawing.
Length in ins.	6.25	7.5
Diam. in inches.	.128	.1295
(i) Within Elastic Limit.		
Torque, ft.-lbs.	3.34	4.08
No. of Turns twisted.	.221	.244
Shearing strength, Tons/sq. in.	43.45	51.5
Modulus of rigidity lbs/sq. in.	6.85×10^6	8.72×10^6
(ii) Beyond elastic limit.		
Torque, ft. lbs.	4.84	5.20
Max. Shearing strength, Tons/sq. in.	63.0	65.75
No. of complete turns.	15.3	19

Curves of the above tests are given in PL. III.

From the above results the first method which we supposed to be superior, unfortunately gives an inferior result. The main cause will most probably be that the wire in the first method was kept too long in molten zinc. In Fig. 13 the first layer has iron-zinc alloy structure of higher content of Fe. than that in Fig. 11. The segregation of ferrite in the first method as shown

in Figs. 14 and 15 is also more serious than that in the first method.

The original nature of the steel in both cases is quite identical. Its micro-structure is shown in Fig. 12. Unfortunately the author was unable to obtain the same ungalvanised steel wire, so that a comparison with naked wire was not possible, but it will be easily understood that the method of galvanisation will very much affect its original strength.

Although I have explained in detail the structure of iron-zinc layers, the perfect formation of the layers is not necessary for the purpose of protection from corrosion, but the essential thing is not to cause any serious alteration in its strength. Thus in such a fine material as the wire, the time of immersing the wire in a zinc-bath and its galvanising method must be carefully studied in order to obtain the most preferable materials.

5. Effect of Galvanisation on Strength.

It will very possibly be understood from the foregoing that the galvanising process will have a great effect on the strength of the steel material, especially if it is a special steel or of minute thickness.

Owing to lack of time, the author could not carry on the test in detail, but the following is an example on a statical test of a mild steel bar.

Item.	Before Galvanisation.	After Galv.
Ultimate strength.	25.2 T/sq. in.	24.0 T/sq.
Yielding Point.	22.0	19.0 „ in.
Elongation on 10 diams.	24.7	25.0 %

As similar reduction of the strength also appears to happen in an alternating stress test.

By alternative application of stress to a galvanised steel, the first hard layer of iron-zinc alloy will be broken into several portions owing to its brittleness, although the zinc layer still keeps an unbroken position. The feature is clearly shown in Fig. 16.

臨

演

亞鉛鍍鋼の組織學的研究外一篇

The author desires to express thanks to Dr. B. P. Haigh, of the Royal Naval College, Greenwich, for his valuable help and suggestion, as well as his kind encouragment, and also to Mr. F. J. A. Pound for his most valuable co-operation.

亞鉛鍍鋼の組織的研究 (Metallurgical Study in Galvanised Steel.)

PL I.

Fig. 1. $\times 200$

Fig. 2 $\times 500$

Fig. 3. $\times 500$

Fig. 4. $\times 500$

Fig. 5. $\times 500$
Time 15 min.

Fig. 6. $\times 300$
Time 15 min.

Fig. 7. $\times 500$
Time 45 min.

Fig. 8. $\times 500$
Time 45 min.

Fig. 9. $\times 400$
Time 60 min.

Fig. 10. $\times 500$.
Time 90 min.

Note:—All etched by Picric Acid vertically illuminated.

Fig. 11.

Fig. 12

Fig. 13.

Fig. 14.

Shewing Segregation of Ferrite.

Fig. 15.

Do. in large scale.

Fig. 16.

Note:—All etched by Picric Acid & illuminated vertically

MxKg Crystallization Curves of Iron-Zinc Alloy.