Title:

Percutaneous Endovascular Retrieval of Large Cement Leakage into the Right Atrium Following Cement-Augmented Pedicle Screw Instrumentation

Authors:

Shinji Takahashi¹, MD, PhD, Etsuji Sohgwawa², MD, Akinobu Suzuki¹, MD, PhD, Akira Yamamoto², MD, PhD, Ryo Sasaki¹, MD, Katsuaki Tanaka³, MD, PhD, Hidetomi Terai¹, MD, PhD, Masatoshi Hoshino¹, MD, PhD, Hiromitsu Toyoda¹, MD, PhD, Koji Tamai¹, MD, PhD, Hiroaki Nakamura¹, MD, PhD

Institutional affiliations

1. Department of Orthopaedic Surgery, Osaka City University Graduate School of Medicine, Osaka, Japan
2. Department of Diagnostic and Interventional Radiology, Osaka City University Graduate School of Medicine, Osaka, Japan
3. Department of Anesthesiology, Osaka City University Graduate School of Medicine, Osaka, Japan

Corresponding author: Shinji Takahashi

Email: shinji@med.osaka-cu.ac.jp

Department of Orthopaedic Surgery, Osaka City University Graduate School of Medicine

Address: 1-4-3 Asahi-machi, Abeno-ku, Osaka 545-8585, Japan

Tel: +81-6-6645-3851

Fax: +81-6-6646-6260

Conflicts of interest:

The authors declare that there are no relevant conflicts of interest.

Author contributions:

Shinji Takahashi, Akinobu Suzuki, and Ryo Sasaki treated this patient, collected the data, and drafted this report. Etsuji Sohgwawa, Akira Yamamoto, and Katsuaki Tanaka treated this patient

and collected the data. Hidetomi Terai, Masatoshi Hoshino, Hiromitsu Toyoda, Koji Tamai, and Hiroaki Nakamura revised the drafted paper. All authors approved the final version for publication.

Sources of financial support: None

IRB approval: This study was approved by the Institutional Review Board of Osaka City University (No. 3170).

Acknowledgments: None

Informed consent: The patient provided informed consent for the publication of their case.

Key words: osteoporosis, cement leakage, percutaneous endovascular retrieval, cement-augmented pedicle screw instrumentation, inferior vena cava, vertebral fracture

Percutaneous Endovascular Retrieval of Large Cement Leakage into the Right

Atrium Following Cement-Augmented Pedicle Screw Instrumentation

Spinal deformities in patients with osteoporosis are difficult to treat because of their debilitating and progressive nature.¹ Such cases often necessitate spinal instrumentation to reduce the back pain or neurological deficit. However, a pedicle screw in the osteoporotic spine poses an increased risk of screw loosening, pullout, and fixation failure. A cement-augmented fenestrated pedicle screw (CAPS) overcomes these problems by improving the initial fixation strength and fatigue strength of instrumentation in osteoporotic vertebrae and offers significant pullout strength.² However, there are several reports of intravascular cement leakage.³ We encountered a case of intravascular long cement leakage following CAPS.

Vertebral column resection (VCR) was planned for a 78-year-old female with osteoporotic vertebral fracture at T12 (Fig 1). The use of CAPS was considered because pedicle screw loosening before surgery was a concern. Pedicle screws were inserted at the T10, T11, L1, and L2 pedicles under fluoroscopy. Expedium Verse® spinal system and Vertecem V+® cement (DePuy Synthes Products, Inc., Raynham, MA, USA) were used. After 4 minutes of mixing, the bone cement was inserted into T10 pedicle screws.

A couple of minutes later, the bone cement was inserted into L2. At this point, we observed long bone cement leakage from the L2 pedicle in fluoroscopy (Fig 2A), into the vein (Fig 2B). The cement gradually moved to the cranial side and stopped at the level of the heart, requiring stoppage of the surgery. At this time, there was no change in blood pressure, heart rate, and electrocardiogram. We consulted a radiologist responsible for the endovascular therapy. Simultaneously, heparin was administered to prevent the formation of thrombosis around the foreign body and subsequent pulmonary artery embolization. Transesophageal echocardiography showed that the migrated cement reached into the right atrium and touched the interatrial septum (Fig 2C). We planned to remove the free cement fragment using a catheter immediately after VCR to avoid the risk of heart wall perforation. The postoperative x-ray showed the migrated cement (Fig 2D and 2E).

The patient was moved from the prone position to the supine position. First, a 16F sheath (Gore® DrySeal, 33 cm) was positioned in the inferior vena cava via the right femoral vein under ultrasound guidance. The retrieval catheter (Merit Medical™ EnSnare® system, 6F) was introduced into the right atrium under fluoroscopic guidance with general anesthesia continued. We successfully captured the migrated cement linear fragment using a triple-loop snare (Fig 3A and B). The object was long (6.5 cm) and

had a needle-like appearance (Fig 3C). Contrast-enhanced CT taken after surgery revealed no evidence of pulmonary embolism and cardiac perforation. The patient's back pain was relieved after surgery, and no further complications occurred.

When used at low viscosity of the bone cement for CAPS, the cement poses a risk of leakage into the venous system.⁴ Janssen et al.⁵ investigated 165 patients who underwent spine surgery with CAPS. They identified 68 cases with cement leakage into paravertebral veins or the ascending vena cava and 13 patients with pulmonary cement embolism (7.9%), of whom five (3.0%) were symptomatic. In addition, a case of cardiac perforation caused by bone cement, closely resembling our situation, was reported as a complication of CAPS,⁶ wherein the authors reported the presence of a sharp and large fragment (4.5-cm-sized and needle-shaped). In their case, the authors detected cement leakage 7 days after spine surgery and performed anterolateral thoracotomy under one-lung ventilation for its removal. In our case, the leakage was spotted during the VCR, and therefore an immediate retrieval procedure using a percutaneous endovascular approach could be planned. Since a linear-shaped cement fragment was fragile to catch by endovascular devices, it was useful to introduce a large bore sheath and use of triple-loop retrieval kits, which were designed with the rigor of inferior vena cava filter retrieval (Fig 3D and 3E). To our knowledge, there have been no studies to

reveal an effective way for the prevention or prediction of cement leakage. A strict indication for CAPS should be necessary to minimize the risk. In addition, CAPS should be used carefully, especially in patients with contraindications for anticoagulation and endovascular treatment.

References

1. Ponnusamy KE, Iyer S, Gupta G, et al. Instrumentation of the osteoporotic spine: Biomechanical and clinical considerations. *Spine J.* 2011;11(1): 54-63.
2. Burval DJ, McLain RF, Milks R, et al. Primary pedicle screw augmentation in osteoporotic lumbar vertebrae: Biomechanical analysis of pedicle fixation strength. *Spine (Phila Pa 1976)* 2007;32(10): 1077-83.
3. Singh V, Mahajan R, Das K, et al. Surgical trend analysis for use of cement augmented pedicle screws in osteoporosis of spine: A systematic review (2000–2017). *Glob Spine J.* 2019;9(7): 783-95.
4. Bohner M, Gasser B, Baroud G, et al. Theoretical and experimental model to describe the injection of a polymethylmethacrylate cement into a porous structure. *Biomaterials.* 2003;24(16): 2721-30.
5. Janssen I, Ryang YM, Gempt J, et al. Risk of cement leakage and pulmonary

73 embolism by bone cement-augmented pedicle screw fixation of the
74 thoracolumbar spine. Spine J. 2017;17(6): 837-44.

75 6. Hong SW, Oh T-H, Jeon JM, et al. Cardiac perforation caused by bone cements
76 as a complication of cement augmented pedicle screw fixation using the
77 fenestrated pedicle screw: A case report. Korean J Neurotrauma. 2020;16(2):
78 337.

79
80
81

Figure legends

Figure 1. A 78-year-old female with an osteoporotic vertebral fracture at T12 presented severe back pain.

Figure 2. Bone cement leakage (yellow arrow) from the L2 pedicle was observed in the lateral view of fluoroscopy (A). Cement leakage (on the right side) into the inferior vena cava (B). Transesophageal echocardiography showed that the migrated cement reached into the right atrium and touched the interatrial septum (C). The post-VCR x-ray showed the migrated cement at heart level (D, E).

Abbreviations: IVC, inferior vena cava; RA, right atrium; SVC, superior vena cava

Figure 3. The migrated cement body (yellow arrow) was captured using a triple-loop snare (white arrow) (A, B). The retrieved object was large (6.5 cm) and had a needle-like appearance (C). Triple-loop retrieval kits, which were designed with the rigor of inferior vena cava filter retrieval, were used (D, E).

Figure 1.

Figure 2.

(A)

(B)

(C)

(D)

(E)

Figure 3.

(A)

(B)

(C)

(D)

(E)